

679 Strander Boulevard • Tukwila, WA 98188-2922 206-575-7494 • FAX 206-575-1193

December 14, 2005

**Rainier Commons** 

To Whom It May Concern:

The following building with each listed area had asbestos abatement performed by Washington State certified asbestos supervisors and workers. Each area was visually inspected by our supervisor upon completion of the abatement activity and was found to be clean; in addition NVL laboratories also performed air clearances per work area. All the work listed below was done per the site-specific contract documents and by Washington State Laws regarding asbestos abatement.

Rainier Commons LLC Property 3100 Airport Way South Seattle, Wa. 98134

Building #9

Thank you,

Project Manager